



NOTICE REGARDING DISCARDED OR ABANDONED CONTAINERS (FORM EQP4476 REV. 4/03))
(Under the authority of Part 201, 1994 Act 451, as amended, and the Rules promulgated thereunder)

Use this form to disclose information related to underground storage tanks (UST) and discarded or abandoned containers required in a Baseline Environmental Assessment (BEA) pursuant to the Part 9 Rules. Submission of this form in a BEA also satisfies the notification requirements of Rule 1015(1) of the Part 10 Rules. This form may also be used, NOT in conjunction with a BEA, to satisfy the notification requirements of Rule 1015(1) of the Part 10 Rules.

All persons providing this notice must complete Section I. Section II must be completed by only those persons who are submitting this form NOT in conjunction with a BEA.

SECTION I

1. Name and Address of person subject to Section 7a:
James Wonacott
Village of Blissfield
408 East Adrian Street
Blissfield, MI 49228
2. Address/location of property where containers are located:
440 East Jefferson
Blissfield, MI 49228
County: Lenawee
3. What is your status relative to the property?
Owner ☒ Current ☐ Prospective ☐
Operator ☐ ☐ ☐
4. Provide a scaled map or drawing of the property that identifies the property boundaries and surrounding property uses. Depict the approximate location(s) of all known discarded or abandoned containers on the drawing. Refer to the locations when completing the attached table.
5. Provide photographs, if practical, that depict the location and general condition of the containers.
6. Complete the attached table.
7. If this form is being submitted in conjunction with a BEA, skip Section II and go to Signature section.

SECTION II

8. Did you previously submit a BEA to the DEQ for this property? ☐ Yes ☐ No
8a. Provide the date the BEA was submitted. _____
8b. Provide the BEA Disclosure or Petition Number, if available. _____
9. Do you anticipate submitting a BEA for the property? ☐ Yes ☐ No
10. Provide the date you became the owner or operator of this property. _____
11. When did you first acquire knowledge of the UST(s) or discarded or abandoned container(s)? _____

With my signature below, I certify that the information provided herein is true and accurate to the best of my knowledge and belief. I understand that intentionally submitting false information to the DEQ is a felony and may result in fines of up to \$25,000 for each violation.

James Wonacott
Signature of owner or operator or person legally authorized by owner or operator
JAMES WONACOTT
Name (typed or printed)

8/6/10
Date
VILLAGE ADMINISTATOR
Title (typed or printed)

Deleted: _____

Deleted: _____

Deleted: _____

Deleted: _____

Deleted: _____

Deleted: _____



MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY
REMEDIAL AND REDEVELOPMENT DIVISION

NOTICE REGARDING UNDERGROUND STORAGE TANKS AND DISCARDED OR ABANDONED CONTAINERS

A	B		D	E	F	G
LOCATION	CONTAINER SIZE AND TYPE	NUMBER OF CONTAINERS	VOLUME OF HAZARDOUS SUBSTANCE(S)	CONTENTS	CONDITION OF CONTAINER	PHOTOS PROVIDED
Area A	1 gal. steel pail	15	0.5 - 1 gal.	Enamel coating	Fair	Yes - Photo 1
Area A	1 gal. steel pail	5	0.5 - 1 gal.	Latex paint	Fair	Yes - Photo 1
Area A	1 gal. steel pail	5	0.5 - 1 gal.	Rust primer	Fair	Yes - Photo 1
Area A	15 gal. plastic poly	1	15 gal.	Sodium hydroxide	Good	Yes - Photo 2
Area A	15 gal. plastic poly	1	7 gal.	Blended phosphate	Good	Yes - Photo 2
Area A	5 gal. plastic pail	1	1 gal.	Depress F anti-foam	Good	Yes - Photo 2
Area A	15 gal. plastic poly	1	3 gal.	Lemonize - cleaner/disinfectant	Container good, but open top	Yes - Photo 2

Deleted: C

Deleted: N

Deleted: MBER

Deleted: 1

EQP4476, Page 2 of 2 (REV. 4/03)

NOTE: THE ABOVE OBSERVATIONS ARE BASED ON A WALKOVER OF THE PROPERTY; HOWEVER, SME DID NOT PHYSICALLY ACCESS THE BUILDINGS ON THE PROPERTY DUE TO THEIR POOR CONDITION. LIMITED OBSERVATIONS WERE MADE THROUGH DOORS AND WINDOWS.



MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY
REMEDATION AND REDEVELOPMENT DIVISION

NOTICE REGARDING UNDERGROUND STORAGE TANKS AND DISCARDED OR ABANDONED CONTAINERS

A	B		D	E	F	G
LOCATION	CONTAINER SIZE AND TYPE	NUMBER OF CONTAINERS	VOLUME OF HAZARDOUS SUBSTANCE(S)	CONTENTS	CONDITION OF CONTAINER	PHOTOS PROVIDED
Area A	5 gal. plastic pail	1	3 gal.	Packaging adhesive	Good	Yes - Photo 2
Area B	55 gal. plastic poly	1 with liquid, three empty	3 gal.	Unknown	Good	Yes - Photo 3
Area C	55 gal. plastic poly	1	5 gal.	Unknown	Good	Yes - Photo 4
Area D	300 gal. plastic? bin	1	200 gal.	Salt (softener?)	Good, but uncovered top	Yes - Photo 5
Area A	5 gal. plastic pail	1	0 gal.	Labeled "concentrated acid"	Good	Yes - Photo 2
Ponds	Surface impoundment	4	seasonal rainwater	seasonal rainwater	N/A	Yes - Photos 6 and 7
Pipe run	Approximately 420 feet long, presumed steel, diam. unknown	1	Unknown, presumed empty	Suspected Cannery process water	Unknown	See diagram.

Deleted: C

Deleted: N

Deleted: MBER

Deleted: ¶

EQP4476, Page 2 of 2 (REV. 4/03)

NOTE: THE ABOVE OBSERVATIONS ARE BASED ON A WALKOVER OF THE PROPERTY; HOWEVER, SME DID NOT PHYSICALLY ACCESS THE BUILDINGS ON THE PROPERTY DUE TO THEIR POOR CONDITION. LIMITED OBSERVATIONS WERE MADE THROUGH DOORS AND WINDOWS.




PHOTO 1 - AREA A



PHOTO 2 - AREA A



PHOTO 3 – AREA B




PHOTO 4 – AREA C



PHOTO 5 – AREA D



PHOTO 6 – POND



PHOTO 7 - POND